

TOP SECRET**PRIORITY 7****TOP SECRET 210049Z**

1965 JUL 21 00 58Z

OUT56226**PRIORITY** **5004**

25X1

IDEALIST**ATTENTION:**

25X1

SUBJECT: EVALUATION OF MISSION C105C**1. CAMERA 119 WAS USED IN MISSION C105C FLOWN ON 12 MARCH 1965.****PROCESSING WAS ACCOMPLISHED IN THE FIELD.****2. ORIGINAL NEGATIVE:****A. EXPOSURE WAS ADEQUATE AND RESOLUTION WAS GOOD.****B. 9R SIDE: THERE IS A SCOTCH TAPE SPLICE BETWEEN FRAMES 288/289. THE CAUSE OF THIS SPLICE APPEARS TO BE A FILM TEAR.****C. 9L SIDE: A SCOTCH TAPE SPLICE BETWEEN FRAMES 250/251 APPEARS TO HAVE BEEN CAUSED BY TORN FILM. ACCOMPANYING THE SPLICE ARE 2 SEVERE CREASES AND OTHER HANDLING MARKS.****D. BOTH SIDES: MINOR EDGE STATIC IS PRESENT ON BOTH THE OUTBOARD AND INBOARD EDGES. ROLLER CHATTER IS APPARENT ON JUST THE INBOARD EDGE. SOME IRREGULAR PLUS DENSITY PROCESSING STREAKS APPEAR INTERMITTENTLY ALONG THE OUTBOARD EDGE OF BOTH SIDES. HEAT SPLICES ARE BETWEEN FRAMES 123/124, 256/257, 389/390, AND 475/476 ON BOTH SIDES. THE FRAMES BETWEEN COUNTER NUMBERS 481 THRU 591 HAVE BEEN EDITED OUT. THE FIRST TITLED FRAME IS 005 AND THE LAST TITLED FRAME IS 510.****E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.****3. POSITIVE:****A. PI SUITABILITY WAS GOOD.****TOP SECRET**

21 JUL 1965

| COPIES RECEIVED | | |
|-----------------|---------|------|
| Cy No. | Office | Act. |
| 1 | File | |
| | OS | |
| | ADMIN | |
| | SEC BR | |
| | P&DS | |
| | CSD | |
| | IPD | |
| | PD | |
| | PSD | |
| | PSD-ICB | |
| 3,4 | TID | |
| | PID | |
| | PAG | |
| | DIAXX-4 | |
| | SPAD | |
| | NSA-LO | |
| | DIA-AP | |

GROUP 1
Excluded from automatic
downgrading and
declassification

25X1

B. PRINTING AND PROCESSING WAS ADEQUATE.

C. CLOUD COVER WAS 0 PERCENT.

T O P S E C R E T

/END OF MESSAGE/

1